



Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

County: Columbia

Agency: REGION 1

ENTRY POINT

EP-A

PWS ID 4100922

VERNONIA, CITY OF

Sample period: April 2021
Month/Year

Number of excursions during this month: 0
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference

Minimum Water Quality
Parameter(s) set for this PWS:

pH 7.3

Print Name: Jell Burch

Signature: Jell Burch

Date: 5-6-21

Send to DWP within 10 days after end of sampling period

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350

Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp

Day	pH	Alk	RAW Alk	Sili	Y/N	<<Have minimums been met for this day?
1						
2						
3						
4						
5						
6						
7	7.3	50.3	5.25		Y	
8						
9						
10						
11						
12						
13						
14	7.4	32.2	25.4		Y	
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						
31						

(No = N = Excursion) Total N's 0