

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pН	Alk	LKAW	FINISH	AN	< <hav< th=""><th>9</th><th>County: Columbia Agency: REGION 1</th><th></th></hav<>	9	County: Columbia Agency: REGION 1	
1						minimu been m	n met for	ENTRY POINT	
2						this day	t.	EP-A	
3						1			and the second
4					eternos terropropropro			PWS ID 4100922	
5								VERNONIA, CITY OF	***************************************
6						4			
7		National County of County States				Sa	mole ne	eriod: July / Zozz Month/Year	
8					hearin marindapani		itipio po	Month/Year	
9									
10					Madharin yan markinin daya	,		a a a a a a a a a a a a a a a a a a a	
11						Nui	nber of (excursions during this month: $\underline{\mathscr{O}}$	EUTOS.
12					NEW THE PARTY STATES			ursions in 6 months is a violation.	
13	7.4		24	28				and Distribution excursions are	
14								. An 'excursion' is any day in which the	
15							er quality by the S	y parameter(s) fall below the minimun	ľ
16						361	by the S	iaio.	
17									
18							Refe	erence	
19				0.0			- A		
20	7.4		25	28			1	Minimum Water Quality	
21					entropos propositions			Parameter(s) set for this PWS:	
22	7 / g.m							pH 7.3	
23	•							7	
24							a de la companya de l		
25									
26	•								
27			ADMILITAR COMMUNICAÇÃO ACADAMA			_		TDD 2 h	
28			httakensejentejeneja velikos kilosaka			Pr	int Nan	ne: Joseph Buch	separat
.30						Si	gnature	e: 1/16-2/1	natural a
31						Da	ate: <u>8</u> -	-10-22	
	N = Exc	ursion	Total	N's	d	Car	nd to DWP	within 10 days after end of sampling perio	od

DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350