

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	RAW	Finish	Y/N
1					
2					
3					
4					
1 2 3 4 5 6 7	7.4		22.5	30,3	4
6	,				
7					
8					
9					
10					
11					
11 12 13 14	7.4		32.0	35.4	Y
13	-				,
14					i k
15					
16	,				
17					
18					
19	7.3		28.2	31.6	Y
20					-
21					
22					
20 21 22 23 24					
24					
25					
26	7.5		25,0	44.7	Y
27					1
28					
29					
30					
31					
No = N	1 = Exc	ursion	) Tota	I N's	ch

	· · · · · · · · · · · · · · · · · · ·					
< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1					
minimums been met for	ENTRY POINT					
this day?	EP-A					
PWS ID 4100922						
VERNONIA, CITY OF						
Sample period: October / 2022						
Month/Year						

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

	um Water Quality eter(s) as set by State
pH Alk	7.3 20.0 (Alkalinity)
	T 00 2 ~1.

Print Name: Jeff Burch	
Signature: Ab Bh	
Date & Phone#://-9-22	_

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/