

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3					
4					
5					-,
1 2 3 4 5 6					
7					
8					
9					
10					
11					
12	7.4	25.1			Y
13		0.00			
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26	7.4	43.1			Y
27					
28					
29					
30					
31					
lo = N	l = Exc	cursion	Tota	N's	\$

<<Have minimums been met for this day?

County: Columbia Agency: REGION 1 ENTRY POINT EP-A

PWS ID 4100922 VERNONIA, CITY OF

Sample period: Apr. / 2.23

Month/Year

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference						
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.3	(Alkalinity)				
Drint Name	tell	Bioli				

Signature:

503-429-6921 Date & Phone#: 5-9-23

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/