

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N
1				130 0400 040 A NORMAN (1905	
3					
4					
5					,
6	7.4	30.3			Y
7					
8					
9				-	
10					
11					
12					
13	7.3	25.1			Y
14					-
15			1		
16					
17					
18					
19					Y
20	7.3	45.2	,		•
21					
22					
23					
24					
25					
26					
27					
28 *	7.4	34.9			Y
29					,
30					
31					
lo = N	1 = Exc	ursion	Tota	l N's	4

< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1				
minimums been met for	ENTRY POINT				
this day?	EP-A				
PWS ID 4100922					
VERNONIA, CITY OF					
Sample pe	eriod: December / 2023  Month/Year				

Number of excursions during this month: 🖄

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.3 Alk 20.0 (Alkalinity)
Print Name: Self Color Signature: 1-3-24  Date & Phone#: 1-3-24
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/