

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2					
3	7.5	29.3			У
4					
5					
6					
7					
8					
9					
10	7.5	33.6	*		У
11					
12					
13					
14					
15					
16					
17	7.4	24.2			У
18					
19					
20					
21					
22					
23					
24	7.4	22.0			X
25					
26					
27					
28					
29					
30					
31					
No = N	1 = Exc	cursion) Tota	l N's	Ø

< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1			
minimums	ENTRY POINT			
been met for				
this day?	EP-A			
PWS ID 4100922				
VERNONIA, CITY OF				
Sample pe	eriod: April 2024			

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Month/Year

		iter Quality as set by State:
pH Alk	7.3	(Alkalinity)

Print Name: CHRIS RICH	IARDSON
Signature: Che RL	
Date & Phone#: 5-7-24	(503)429-6921
Send to DWP within 10 da	ys after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/