

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1	gar vere i i i engliga de arti		THE RESERVE TO SERVE THE		Andrea Albertania
2					
3					
4	7.3	31.3			Y
5					
6					,
7					
8					
9					
10					
11	7.4	33.6			Y
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24 25					
25	7.4	37.1			V
26					
27					
28					
29					
30					
31					
(No = N	l = Exc	ursion	Total	l N's	Ø

< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1					
minimums	ENTRY POINT					
been met for						
this day?	EP-A					
PWS ID 4100922						
VERNONIA, CITY OF						
Sample period: Scot. 2024						
	Month/Year					

Number of excursions during this month: _

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

-Reference						
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.3	(Alkalinity)				

Print Name: CHRIS RICHARDSON
Signature: CL nL
Date & Phone#: 10-8-24 429-6921
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/