

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1					
2	7.3	25,3			Y
3					
4					
5					
6					
7					
8					
9	7.4	23.4			Y
10					
11					
12					NOTICE THE PROPERTY OF THE PRO
13					
14					CONTRACTOR DE LA CONTRA
15	7.4	24.1			У
16					
17					
18					
19					
20					
21	7.4	25.2			У
22			**************************************		
23					
24			Control of the contro		ì
25					
26					
27					
28					
29	7.3	23.0			У
30					
31		The second secon	Total		

< <have< th=""><th>County: Columbia Agency: REGION 1</th><th></th></have<>	County: Columbia Agency: REGION 1	
minimums	ENTRY POINT	
been met for this day?	EP-A	
	PWS ID 4100922	
	VERNONIA, CITY OF	
Sample ne	riod: Tan 1025	

Number of excursions during this month: ____

Month/Year

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference						
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.3	(Alkalinity)				

Print Name: <u>CHRIS</u> RICHARDSON
Signature: CL RL
Date & Phone#: 503-429-6921 /2-7-25
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/