

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other	Y/N	
1						
2					-	
3						
4						
1 2 3 4 5	7.4	24.8			y	
6						
7						
8						
9						
10						
11						
12	7.4	22.4			γ	
13						
14						
15						
16						
17						
18						
19	7.3	22.9	CO CALLED STATE OF THE STATE OF		y	
20						
21						
22			ATTERNETALINA			
23						
24						
25						
26						
27						
28	7,3	23			Y	
29						
30						
31	-		-			
o = N = Excursion) Total N's						

<<Have
minimums
been met for
this day?</pre>

County: Columbia Agency: REGION 1

ENTRY POINT

EP-A

PWS ID 4100922

PWS 1D 4100922 VERNONIA, CITY OF

Sample period: February / 2025

Month/Year

## Number of excursions during this month: \_

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference					
Minimum Water Quality Parameter(s) as set by State:					
pH Alk	7.3 20.0 (Alkalinity)				

Print Name: CHRIS RICHARDSON

Signature: Chr.

Date & Phone#: 3/10/25 503-429-6921

Send to DWP within 10 days after end of

sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/