

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1				er Armena ar value and the c	entre blenkejenen
2					
2 3 4					
4					
5					
6					
7	7.3	28.9			Y
8					
9					
10					
11					
12					
13					
14					
15	7.4	34.9			Y
16					
17					
18					
19					
20					
21					
22 23	7.4	28.1			Y
23					
24					
25					
26					
27 28					
28	7.4	23.4			Y
29					
30					
31					
10 = N	l = Exc	ursion)	Total	N's	Cop

< <have< td=""><td>County: Columbia Agency: REGION 1</td><td></td></have<>	County: Columbia Agency: REGION 1				
minimums	ENTRY POINT				
been met for					
this day?	EP-A				
PWS ID 4100922					
VERNONIA, CITY OF					
Sample period: May - 2025					
Month/Year					

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference			
Minimum Water Quality Parameter(s) as set by State:			
pH 7.3 Alk 20.0 (Alkalinity)			
Print Name: Jest Buch			

Date & Phone#: 6-10-25 503-429-69
Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

Signature: /