

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N
1		Summittee Light Continues on the		Charles and Colympical Laborator	
2					
3					
4	7.4	25.2			7
5	,				
6					
7					
8					
9					
10					
11	7.4	28.1			Y
12		•			
13					
14					
15					
16					
17					
18	7.4	21.4			Y
19					
20					
21					
22					
23					
24					
25	7.3	23.1			γ
26					
27					
28					
29					
30					
31					

< <have< td=""><td>County: Columbia Agency: REGION 1</td></have<>	County: Columbia Agency: REGION 1			
minimums	ENTRY POINT			
been met for				
this day?	$\mathbf{EP-A}$			
PWS ID 4100922				
VERNONIA, CITY OF				
Sample pe	riod: June 2025			
Month/Year				

Number of excursions during this month:

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference
Minimum Water Quality Parameter(s) as set by State:
pH 7.3 Alk 20.0 (Alkalinity)
Print Name: Jeff Book
Signature: (4)
Date & Phone#: 7-10-25 503-429-192

Send to DWP within 10 days after end of

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

sampling period