

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

	Day	рН	Alk	Phos	Other	Y/N	
	1					A COLUMN STORE	
	2						
	2 3 4 5						
	4						
	6						
	7						
	8						
	9	7.5	24.8			Y	
	10					-	
	11						
	12						
	13						
	14						
	15						
-	16 '	7.3	25.1			Y	
	17						
ĺ	18						
ĺ	19						
	20						
	21						
	22						
	23	7.4	22.5			Y	
	24						
	25						
	26						
	27						
	28						
	29						
	30	7.3	443			Y	
	31					ę.	
(N	(No = N = Excursion) Total N's						

	7				
< <have< td=""><td>County: Columbia Agency: REGION 1</td><td></td></have<>	County: Columbia Agency: REGION 1				
minimums	ENTRY POINT				
been met for					
this day?	EP-A				
PWS ID 4100922					
	VERNONIA, CITY OF				
Sample period: July 2025					

Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the

Reference -	***************************************					
Minimum Water Quality Parameter(s) as set by State:						
pH Alk	7.3	(Alkalinity)				
		\				

Send to DWP within 10 days after end of sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/

State.