



Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.7				Y
2	7.7				Y
3	7.6				Y
4					
5					
6	7.6				Y
7	7.7				Y
8	7.7				Y
9					
10	7.6				Y
11	7.5				Y
12	7.5				Y
13	7.6				Y
14	7.7				Y
15					
16	7.7				Y
17	7.6				Y
18	7.6				Y
19	7.7				Y
20					
21	7.7				Y
22	7.7				Y
23	7.6				Y
24					
25	7.6				Y
26	7.5				Y
27	7.6				Y
28	7.7				Y
29					
30					
31	7.6				Y

(No = N = Excursion) Total N's 2

<<Have
minimums
been met for
this day?

County: Lincoln

Agency: REGION 2

ENTRY POINT

EP- A

PWS ID 4100925

SW LINCOLN CO WATER DIST

Sample period: March 7 to 25

Month/Year

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation.
Entry Point and Distribution excursions are
cumulative). An 'excursion' is any day in which the
water quality parameter(s) fall below the minimum
set by the State.

Reference

**Minimum Water Quality
Parameter(s) as set by State:**

pH 7.1

Print Name: Leah Karcis

Signature: [Signature]

Date Phone#:

4/1/25 541-547-3315

**Send to DWP within 10 days after end of
sampling period**

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350
Phone (971) 673-0405 Website: <http://oregon.gov/DHS/ph/dwp/index.shtml>