

Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""><th></th></have<>		
1						minimums	County: Lincoln Agency: REGION 2	
2						been met for	ENTRY POINT	
3						this day?	EP-B	
4							PWS ID 4100925	
5						SW LINCOLN CO WATER DIST		
6						F		
7							riod: NOVEmber 2021	
8						Month/Year		
9						Ţ	wonu/rear	
10						Number of excursions during this month: (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An 'excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.		
11								
12								
13		1						
14								
15		2.						
16								
17					-	Reference		
18.								
19		1				M	inimum Water Quality	
20						Parameter(s) as set by State:		
21							pH 7.1	
2			-					
3	1.6				Y		11	
4								
5			i. de		_			
6								
7						Print Nan	ne: BARRY ARNOLD	
8						Signature	: Barry Arnold	
9					-	Date Pho	one#:12-9-2, 541-547-3315	
0					_		WP within 10 days after end of	
1			Fotal N			sampling		

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml