

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Sili	Y/N	< <have< th=""><th>Country I have been a second as a second a</th></have<>	Country I have been a second as a second a	
1						minimums	County: Lincoln Agency: REGION 2	
2					$\Box$	been met for	ENTRY POINT	
3					T	this day?	EP-B	
4							PWS ID 4100925	
5						SW LINCOLN CO WATER DIST		
6							EMICOEM CO WATER DIST	
7							T. J. V. 2.22	
8	6				y	Sample period: February 2022		
9			- 1				Month/Year	
10						Number of ex	cursions during this month:	
11	7.5				1	(Over 9 excurs	sions in 6 months is a violation.	
12		-				Entry Point and	d Distribution excursions are	
13						cumulative). A	n 'excursion' is any day in which the	
14	7.5				X	water quality p	arameter(s) fall below the minimum	
15						set by the State	θ.	
16								
17	7.5				X	Referen	ice	
18								
19						M	inimum Water Quality	
20						Pa	arameter(s) as set by State:	
21							pH 7.1	
23	7/				V	•		
24	16	,			2			
25								
26					-			
27	-		-	-	$\dashv$			
28			-+		_	Print Nan	ne: BARRY ARNOLD	
29		-+		-+			: Barry Arnold	
30	-	-			-		one#: 3-4-02. 541-547-3315	
31		-			-	Send to D	WP within 10 days after end of	
			Total N			sampling		

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml