



# Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1					
2					
3	7.5				Y
4					
5	7.4				Y
6					
7					
8					
9					
10					
11					
12	7.4				Y
13					
14					
15					
16					
17	7.2				Y
18					
19					
20					
21					
22					
23					
24					
25	7.3				Y
26	7.2				Y
27					
28					
29					
30	7.5				Y
31					

<<Have  
minimums  
been met for  
this day?

County: Lincoln Agency: REGION 2

**ENTRY POINT**

**EP- B**

**PWS ID 4100925**

**SW LINCOLN CO WATER DIST**

**Sample period:** September 2025  
Month/Year

**Number of excursions during this month:** 0

*(Over 9 excursions in 6 months is a violation.  
Entry Point and Distribution excursions are  
cumulative). An 'excursion' is any day in which the  
water quality parameter(s) fall below the minimum  
set by the State.*

**Reference**

**Minimum Water Quality  
Parameter(s) as set by State:**

pH 7.1

**Print Name:** Rick McChung  
**Signature:** Rick McChung  
**Date Phone#:** 10/1/25 541-547-3315  
**Send to DWP within 10 days after end of  
sampling period**

(No = N = Excursion) **Total N's** 0

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
Phone (971) 673-0405 Website: <http://oregon.gov/DHS/ph/dwp/index.shtml>