

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Sili	Y/N	< <have< th=""></have<>
i	7.4				Y	minimums FNTRY POINT
2	7.4				Y	for this day?  A
3	7.4	-			Y	
4	7.5		,		4	PWS ID 4100926
5	7.4				Y	WALDPORT, CITY OF
6	7.4	32			Y	
7	7.5				14	Sample period: $07/21$
8	7.5				Y	Month/Year
9	7.4				7	Number of excursions* during this month:
10	7.5				7	(Count the number of days when any WQP was less
12	7.5				4	than the minimum required)
13	7.4				4	
14	7.4				Y	Total excursions during the previous 5 months:
15	7.4				Y	(Over 9 excursions in 6 months is a violation. Entry
16	7.4				4.	Point and Distribution excursions are cumulative )
17	7,5		7 .		4	Is system in compliance? (Y)/ N
18	7.5				4	
19	7.6	35			4	-Reference
20	7.6			,	7	
21	7,5	,			7	Minimum Water Quality
77	7.5				7	Parameters as set by State:
23	7.4				4	pH 7.2
25	7.5				4	:
26	7.4				Y	
27	7.4	1			Y	
28	7.5				Ý	
79	7.5				4	$ \uparrow$ $\downarrow$
30	7.5				Y	Print Name: Lyle T. Arrant
31	7.5			ъ	7	Signature: Juli 1. Misunt
(No = N = Excursion) Total N's Date: 08/83/21						
				•		Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-438