



## Lead &amp; Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.5				Y
2	7.6				Y
3	7.6				Y
4	7.6				Y
5	7.6				Y
6	7.6				Y
7	7.6				Y
8	7.6				Y
9	7.6				Y
10	7.5				Y
11	7.6				Y
12	7.6	19			Y
13	7.6				Y
14	7.5				Y
15	7.5				Y
16	7.5				Y
17	7.5				Y
18	7.5				Y
19	7.6				Y
20	7.6				Y
21	7.5				Y
22	7.5				Y
23	7.5				Y
24	7.5				Y
25	7.5	20			Y
26	7.5				Y
27	7.5				Y
28	7.5				Y
29	7.5				Y
30	7.5				Y

<<Have  
minimums  
been met  
for this day?

## ENTRY POINT

A

PWS ID 4100926

WALDPOR, CITY OF

Sample period:

4/23

Month/Year

Number of excursions\* during this month: 0

(Count the number of days when any WQP was less  
than the minimum required)

Total excursions during the previous 5 months: 0

(Over 9 excursions in 6 months is a violation. Entry  
Point and Distribution excursions are cumulative)

Is system in compliance? Y/N

Reference

Minimum Water Quality  
Parameters as set by State:

pH 7.2

Print Name:

Lytle T. Arvant

Signature:

Lytle T. Arvant

Date: 05/04/23

(No = N = Excursion) Total N's: 0

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4368