



Water Quality Parameter Monitoring Form
Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.6				y
2	7.6				y
3	7.5				y
4	7.5				y
5	7.6				y
6	7.6				y
7	7.6				y
8	7.4				y
9	7.4				y
10	7.5	30			y
11	7.6				y
12	7.4				y
13	7.5				y
14	7.3				y
15	7.4				y
16	7.3				y
17	7.6				y
18	7.5				y
19	7.6				y
20	7.6				y
21	7.6				y
22	7.7				y
23	7.4	30			y
24	7.4				y
25	7.5				y
26	7.5				y
27	7.5				y
28	7.5				y
29	7.5				y
30	7.4				y
31	7.6				y

(No = N = Excursion) Total N's **N**

<<Have
minimums
been met
for this day?

ENTRY POINT

A

PWS ID 4100926

WALDPORT, CITY OF

Sample period: December 2024
Month/Year

Number of excursions* during this month: 0
(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: 0
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Is system in compliance? Y N

—Reference—

Minimum Water Quality
Parameters as set by State:

pH 7.2



Print Name: Lyle T. Arrant
Signature: Lyle T. Arrant
Date: 1/03/25

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4358