



Water Quality Parameter Monitoring Form  
**Lead & Copper Rule Corrosion Control**

Day	pH	Alk	Phos	Sili	Y/N
1	7.5				y
2	7.6				y
3	7.4				y
4	7.4				y
5	7.4				y
6	7.5				y
7	7.5	28			y
8	7.4				y
9	7.5				y
10	7.4				y
11	7.3				y
12	7.4				y
13	7.5				y
14	7.6				y
15	7.5				y
16	7.5				y
17	7.5				y
18	7.5				y
19	7.5				y
20	7.6	25			y
21	7.5				y
22	7.6				y
23	7.5				y
24	7.5				y
25	7.5				y
26	7.5				y
27	7.5				y
28	7.6				y
29	7.5				y
30	7.5				y
31	7.6				y

<<Have minimums been met for this day?

**ENTRY POINT**

**A**

**PWS ID 4100926**

**WALDPOR, CITY OF**

Sample period: DEC 2025  
 Month/Year

Number of excursions\* during this month: \_\_\_\_\_  
 (Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: \_\_\_\_\_  
 (Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Is system in compliance? (Y) / N

—Reference—

Minimum Water Quality Parameters as set by State:

pH 7.2



(No = N = Excursion) Total N's 0

Print Name: James Ledbetter

Signature: James Ledbetter

Date: 1-6-2026

Send to OHD within 10 days after end of sampling p

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-