



Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.6				
2	7.5	25			
3	7.6				
4	7.6				
5	7.5				
6	7.4				
7	7.5				
8	7.6				
9	7.5				
10	7.6				
11	7.7				
12	7.5				
13	7.5				
14	7.4				
15	7.4	25			
16	7.5				
17	7.4				
18	7.5				
19	7.4				
20	7.5				
21	7.6				
22	7.5				
23	7.6				
24	7.6				
25	7.6				
26	7.6				
27	7.5				
28	7.6	28			
29	7.6				
30	7.6				
31	7.6				

<<Have minimums been met for this day?

ENTRY POINT

A

PWS ID 4100926

WALDPOR, CITY OF

Sample period: Jan 2026
Month/Year

Number of excursions* during this month: _____
(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: _____
(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Is system in compliance? Y N

Reference _____

Minimum Water Quality Parameters as set by State:

pH

(No = N = Excursion) Total N's

Print Name: James Ledbetter

Signature: James Ledbetter

Date: 2-4-2026

Send to OHD within 10 days after end of sampling p

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-