



# Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N
1	7.4				Y
2	7.5				Y
3	7.4				Y
4	7.4				Y
5	7.4				Y
6	7.5				Y
7	7.5	25			Y
8	7.4				Y
9	7.4				Y
10	7.5				Y
11	7.5				Y
12	7.5				Y
13	7.5				Y
14	7.4				Y
15	7.4				Y
16	7.4				Y
17	7.5				Y
18	7.6				Y
19	7.6				Y
20	7.6				Y
21	7.5	24			Y
22	7.5				Y
23	7.5				Y
24	7.5				Y
25	7.5				Y
26	7.5				Y
27	7.5				Y
28	7.5				Y
29	7.5				Y
30	7.5				Y
31	7.5				Y

<<Have minimums been met for this day?

## ENTRY POINT

A

PWS ID 4100926

WALDPOR, CITY OF

Sample period: \_\_\_\_\_

10/21

Month/Year

Number of excursions\* during this month: 0

(Count the number of days when any WQP was less than the minimum required)

Total excursions during the previous 5 months: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

Is system in compliance? (Y) N

Reference \_\_\_\_\_

Minimum Water Quality Parameters as set by State:

pH 7.2

Print Name: Lyle T. Arrant

Signature: Lyle T. Arrant

Date: 11/04/21

(No = N = Excursion) Total N's 0

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381