



Lead & Copper Rule Corrosion Control

| Day | pH | Alk | Phos | Sili | Y/N |
|-----|-----|-----|------|------|-----|
| 1 | 7.5 | | | | Y |
| 2 | 7.3 | | | | Y |
| 3 | 7.6 | | | | Y |
| 4 | 7.5 | | | | Y |
| 5 | 7.6 | | | | Y |
| 6 | 7.2 | | | | Y |
| 7 | 7.6 | | | | Y |
| 8 | 7.6 | | | | Y |
| 9 | 7.7 | | | | Y |
| 10 | 7.6 | | | | Y |
| 11 | 7.7 | 25 | | | Y |
| 12 | 7.4 | | | | Y |
| 13 | 7.5 | | | | Y |
| 14 | 7.6 | | | | Y |
| 15 | 7.7 | | | | Y |
| 16 | 7.7 | | | | Y |
| 17 | 7.7 | | | | Y |
| 18 | 7.7 | | | | Y |
| 19 | 7.5 | | | | Y |
| 20 | 7.5 | | | | Y |
| 21 | 7.5 | | | | Y |
| 22 | 7.7 | | | | Y |
| 23 | 7.7 | | | | Y |
| 24 | 7.6 | 22 | | | Y |
| 25 | 7.5 | | | | Y |
| 26 | 7.6 | | | | Y |
| 27 | 7.5 | | | | Y |
| 28 | 7.5 | | | | Y |
| 29 | 7.6 | | | | Y |
| 30 | 7.6 | | | | Y |
| 31 | 7.5 | | | | Y |

<<Have
minimums
been met
for this day?

ENTRY POINT

A

PWS ID 4100926

WALDPOR, CITY OF

Sample period: 08/22
Month/Year

Number of excursions* during this month: 0
(Count the number of days when any WQP was less
than the minimum required)

Total excursions during the previous 5 months: 0
(Over 9 excursions in 6 months is a violation. Entry
Point and Distribution excursions are cumulative)
Is system in compliance? Y N

Reference

Minimum Water Quality
Parameters as set by State:

pH 7.2(No = N = Excursion) Total N's 0

Print Name: Lyle T. Arrant
Signature: Lyle T. Arrant
Date: 09/01/22

Send to OHD within 10 days after end of sampling period

Oregon Health Division, PO Box 14350, Portland, OR 97293-0350 Phone (503) 731-4381