

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?	
	pH	Alk	Y/N	pH	Alk	Y/N	
1	7.57		y	7.57		y	
2	7.63		y	7.97		y	
3	7.61		y	7.85		y	
4	7.59		y	7.69		y	
5	7.61		y	7.55		y	
6	7.69		y	7.68		y	
7	7.71	48	y	7.72	47	y	
8	7.76		y	7.84		y	
9	7.80		y	7.91		y	
10	7.83		y	7.89		y	
11	7.81		y	7.65		y	
12	7.79		y	7.79		y	
13	7.77		y	7.85		y	
14	7.68	46	y	7.75	44	y	
15	7.85		y	7.75		y	
16	7.57		y	7.70		y	
17	7.62		y	7.73		y	
18	7.40		y	7.71		y	
19	7.63		y	7.80		y	
20	7.55	45	y	7.41	42	y	
21	7.63		y	7.41		y	
22	7.58		y	7.82		y	
23	7.58		y	7.78		y	
24	7.62		y	7.75		y	
25	7.57		y	7.79		y	
26	7.58	36	y	7.51	37	y	
27	7.51		y	7.57		y	
28	7.50		y	7.63		y	
29	7.57		y	7.58		y	
30	7.65		y	7.68		y	
31	7.57		y	7.78		y	
<b>Total N's</b>			<b>0</b>				<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Oct-21

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0


(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R. Briggs

**Signature:** 

**Date:** 11/1/2011

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405