

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.62	34	y	7.68	33	y
2	7.67		y	7.74		y
3	7.63		y	7.75		y
4	7.50		y	7.65		y
5	7.45		y	7.41		y
6	7.55		y	7.60		y
7	7.63		y	7.86		y
8	7.60	32	y	7.60	36	y
9	7.62		y	7.55		y
10	7.60		y	7.73		y
11	7.64		y	7.87		y
12	7.64		y	7.78		y
13	7.61		y	7.76		y
14	7.69		y	7.62		y
15	7.59		y	7.80		y
16	7.57	33	y	7.75	35	y
17	7.57		y	7.74		y
18	7.48		y	7.46		y
19	7.43		y	7.48		y
20	7.60		y	7.51		y
21	7.59		y	7.54		y
22	7.54	36	y	7.63	36	y
23	7.57		y	7.69		y
24	7.51		y	7.85		y
25	7.50		y	7.75		y
26	7.52		y	7.84		y
27	7.48		y	7.52		y
28	7.52	36	y	7.62	38	y
29	7.46		y	7.79		y
30	7.56		y	7.64		y
31						
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Jun-22

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)


**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

Minimum Water Quality Parameters as set by OHA		
	EP	DIST
pH	7.2	7.2
Alk		(Alkalinity)
PO4		(Orthophosphate)
Other		( )

**Print Name:** Justin R. Riggs

**Signature:** 

**Date:** 7/11/2022

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405