

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point			Distribution			
	pH	Alk	≥Min?	pH	Alk	≥Min?	
1	7.64		y	7.96		y	
2	7.62		y	7.83		y	
3	7.60	40	y	7.75	41	y	
4	7.61		y	7.68		y	
5	7.64		y	7.53		y	
6	7.63		y	7.82		y	
7	7.76		y	7.74		y	
8	7.79		y	7.50		y	
9	7.74		y	7.86		y	
10	7.69		y	7.65		y	
11	7.70		y	7.72		y	
12	7.63	47	y	7.75	50	y	
13	7.66		y	7.88		y	
14	7.72		y	7.89		y	
15	7.66		y	8.07		y	
16	7.62		y	8.04		y	
17	7.66		y	7.63		y	
18	7.61		y	7.70		y	
19	7.64	47	y	7.64	48	y	
20	7.64		y	7.71		y	
21	7.59		y	7.78		y	
22	7.39		y	7.34		y	
23	7.62		y	7.78		y	
24	7.62		y	7.81		y	
25	7.57		y	7.67		y	
26	7.56		y	7.63		y	
27	7.55	39	y	7.65	45	y	
28	7.58		y	7.65		y	
29	7.58		y	8.08		y	
30	7.61		y	7.94		y	
31	7.58		y	7.78		y	
<b>Total N's</b>			<b>0</b>				<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Oct-22

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

Minimum Water Quality Parameters as set by OHA		
	EP	DIST
pH	7.2	7.2
Alk		(Alkalinity)
PO4		(Orthophosphate)
Other		( )

**Print Name:** Justin R. Riggs

**Signature:** *Justin R. Riggs*

**Date:** 11/4/2022

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405