

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.64		y	7.66		y
2	7.57	38	y	7.75	39	y
3	7.75		y	8.09		y
4	7.66		y	7.87		y
5	7.75		y	7.82		y
6	7.73		y	8.05		y
7	7.78	38	y	7.90	39	y
8	7.83		y	7.87		y
9	7.85		y	7.67		y
10	7.72		y	7.90		y
11	7.57		y	8.00		y
12	7.71		y	7.81		y
13	7.66		y	7.80		y
14	7.67		y	7.60		y
15	7.59		y	7.69		y
16	7.69	39	y	7.75	40	y
17	7.74		y	7.79		y
18	7.69		y	7.77		y
19	7.66		y	8.05		y
20	7.57		y	7.55		y
21	7.66	41	y	7.87	42	y
22	7.65		y	7.72		y
23	7.63		y	7.80		y
24	7.65		y	7.89		y
25	7.64		y	7.99		y
26	7.68		y	7.61		y
27	7.62		y	7.65		y
28	7.64	41	y	7.69	42	y
29	7.67		y	7.76		y
30	7.64		y	7.80		y
31						
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Jun-23

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R Riggs

**Signature:** *Justin R Riggs*

**Date:** 7/6/2023

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405