

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.64		y	7.76		y
2	7.55		y	8.00		y
3	7.66		y	7.77		y
4	7.69		y	7.98		y
5	7.70		y	7.92		y
6	7.62		y	7.66		y
7	7.61		y	7.75		y
8	7.60		y	8.01		y
9	7.54		y	7.98		y
10	7.55		y	7.67		y
11	7.66		y	7.69		y
12	7.69	44	y	7.79	43	y
13	7.60		y	7.68		y
14	7.58		y	7.71		y
15	7.58		y	7.65		y
16	7.63		y	7.93		y
17	7.60		y	7.80		y
18	7.52		y	7.65		y
19	7.57		y	7.57		y
20	7.63	45	y	7.60	45	y
21	7.66		y	7.65		y
22	7.59		y	7.71		y
23	7.63		y	7.65		y
24	7.60		y	7.68		y
25	7.67		y	7.72		y
26	7.68		y	7.80		y
27	7.60	42	y	7.67	45	y
28	7.67		y	7.90		y
29	7.63		y	7.98		y
30	7.62		y	7.60		y
31	7.54		y	7.77		y
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*?

**PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Jul-23

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R. Misses

**Signature:** *Justin R. Misses*

**Date:** 8/1/2023

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405