

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point		≥Min?	Distribution		≥Min?
	pH	Alk	Y/N	pH	Alk	Y/N
1	7.56		y	7.73		y
2	7.65		y	7.76		y
3	7.62	47	y	7.71	47	y
4	7.63		y	7.74		y
5	7.73		y	8.07		y
6	7.65		y	8.04		y
7	7.66		y	7.80		y
8	7.65	44	y	7.75	47	y
9	7.68		y	7.56		y
10	7.63		y	7.73		y
11	7.60		y	7.67		y
12	7.61		y	7.90		y
13	7.59		y	7.76		y
14	7.60		y	7.64		y
15	7.58		y	7.69		y
16	7.63		y	7.89		y
17	7.61	44	y	7.68	50	y
18	7.55		y	7.76		y
19	7.60		y	7.85		y
20	7.61		y	7.87		y
21	7.60		y	7.66		y
22	7.68		y	7.68		y
23	7.62	40	y	7.62	40	y
24	7.63		y	7.63		y
25	7.60		y	7.65		y
26	7.63		y	7.99		y
27	7.42		y	7.53		y
28	7.58		y	7.85		y
29	7.56		y	7.83		y
30	7.64	42	y	7.70	44	y
31	7.56		y	7.56		y
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Aug-23

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R Riggs

**Signature:** *Justin R Riggs*

**Date:** 9/5/2023

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405