

## Water Quality Parameter Monitoring Form Lead & Copper Rule Corrosion Control

Day	Entry Point			Distribution		
	pH	Alk	≥Min? Y/N	pH	Alk	≥Min? Y/N
1	7.64		y	7.65		y
2	7.69		y	7.55		y
3	7.64		y	7.68		y
4	7.72	44	y	7.94	44	y
5	7.63		y	7.83		y
6	7.68		y	7.67		y
7	7.67		y	7.83		y
8	7.68		y	7.90		y
9	7.65		y	7.76		y
10	7.65		y	7.75		y
11	7.69		y	7.72		y
12	7.65	20	y	7.77	46	y
13	7.43		y	7.66		y
14	7.67		y	7.85		y
15	7.60		y	7.90		y
16	7.58		y	7.66		y
17	7.63		y	7.74		y
18	7.71		y	7.65		y
19	7.69	45	y	7.58	45	y
20	7.69		y	7.81		y
21	7.67		y	7.99		y
22	7.61		y	7.64		y
23	7.73		y	7.99		y
24	7.63		y	8.00		y
25	7.73	46	y	7.73	43	y
26	7.66		y	7.81		y
27	7.54		y	7.62		y
28	7.64		y	7.92		y
29	7.68		y	7.85		y
30	7.66		y	7.61		y
31	7.65		y	7.72		y
<b>Total N's</b>			<b>0</b>			<b>0</b>

(NO = N = Excursions)

**ENTRY POINT**

<<Have minimums been met for this day\*? **PWS ID:** 41 0 0 9 5 3

**System Name:** City of Willamina

**Entry Point:** A

**Sample Period:** Oct-23

**Number of excursions during this month:** 0

(Count the number of days when any WQP was less than the minimum required)

**Total excursions during previous 5 months:** 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative)

*For OHA use only*

**Minimum Water Quality Parameters as set by OHA**

	EP	DIST	
pH	7.2	7.2	
Alk			(Alkalinity)
PO4			(Orthophosphate)
Other			( )

**Print Name:** Justin R. Weiss

**Signature:**

**Date:** 11/7/2023

\*Entry point monitoring must be done at a minimum of once every two weeks, however, this form may be used for more frequent sampling.

Send to DWS within 10 days after end of the sampling period to:  
OHA-Drinking Water Services, PO Box 14350, Portland, Or 97293-0350 Phone (971) 673-0405