

Water Quality Parameter Monitoring Form

# Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Other	Y/N
1	7.3				N
2	7.6				N
3	7.6				N
4	7.4				N
5	7.1				N
6	7.5				N
7	7.4				N
8	7.4				N
9	7.6				N
10	7.5				N
11	7.2				N
12	7.3				N
13	7.6				N
14	7.4				N
15	7.3				N
16	7.3				N
17	7.6				N
18	7.5				N
19	7.5				N
20	7.4				N
21	7.2				N
22	7.2				N
23	7.3				N
24	7.5				N
25	7.4				N
26	7.3				N
27	7.5				N
28	7.4				N
29	7.4				N
30	7.5				N
31	7.7				N
No = N = Excursion) Total N's					0





**Number of excursions\* during this month: 0**

*(Count the number of days when any WQP was less than the minimum required)*

**Total excursions during the previous 5 months: 0**

*(Over 9 excursions in 6 months is a violation.*

*EntryPoint and Distribution excursions are cumulative )*

**Print Name:     Rick McClung**

**Signature: \_\_\_\_\_**

**Date:     2/10/2021**

\_\_\_\_\_

Send to DWP within 10 days after end of sampling period  
OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
Phone (971) 673-0405 Website: <http://healthoregon.org/dwp/>