

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""><th></th><th></th><th></th><th></th><th></th><th></th><th></th></have<>							
1	7.4				Y	minimur	ms		ENT	RY	POIN	T	
2	7.3				4	been me		PWS I	D: 11	(2)			
3	7.3				·/	this day						6 6	
4	7,3				Y			ame: <u>(</u>		ot	Yacl		
5	7.3				4	Ent	try Poir	nt: <u>_</u>	1200	18	1705	pect	
6	7.3				У	Sar	mple Pe	eriod:_	Mai	rch	20	122	
7	7.3				Y					Monti	h/Year		
8	7.4				Y	Number	r of exc	cursion	s* du	rina t	his mo	onth:	3
9	74				4	(Count t							3
10	7,3				Y	less that							
11	7,5				У								
12	7,5				4	Total ex	ccursio	ns duri	ing th	e pre	vious	5 mont	hs:
13	7,5				Y	(Over 9	excursi	ions in (6 mon	ths is	a viola	tion. E	ntry
14	7.5				Y	Point an							
15	7,4				Y		_For O	مالا ۸ الام	only				
16	7.5				У		-F01 C)HA use	Orny				
17	7.4				У			Minin	aum V	Vator	Qualit		
18	7,4				Y				neters			.y	
19	7.1				У			_		7	cray		
20	7.1				Y			pН	7.0				
21	7.2				Y			Alk		_	alinity)		
22	7.3				Y			PO4		(Orth	nophos	sphate)	
23	7,4				Y			Other]()	
24	73			2	У								
25	7.5				Y	l							
26	7.5				Y								
27	7,5				Y		Print N	lomoi	P .:	Kr	NCM	1	1,
28	7,5				У		Signat		911	WAI A	1	HONO	1
29	7.4				Y		Date:	ure.	1/2	1-1			
30	7.4				Y			DIAG	0/20	10:	F.		
31	7.4				Y			o DWP		10 da	ays atte	er end o	o†
(No = N	V = Exc	cursion) Tota	l N's	Ø	ē	sampili	ng perio	u				

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/