

## Lead & Copper Rule Corrosion Control

AUTHORITY

County: Josephine	Agency: 5
<b>Entry Point</b>	
A	
PWS ID 4100971	
Cave Junction, City of	
Sample Period:	
Month/Year Apr. 2022	

Day	Ph	Alk	Phos	Sili	Y/N	<< Have Minimums Been Met for this day
1	7.5				Y	
2						
3						
4	7.3				Y	
5						
6	7.4				Y	
7						
8	7.3				Y	
9						
10						
11	7.4				Y	
12						
13						
14	7.4				Y	
15						
16						
17						
18	7.4				Y	
19						
20	7.4				Y	
21						
22	7.4				Y	
23						
24						
25	7.3				Y	
26						
27	7.3				Y	
28						
29						
30						
31						
No = N = Excursion					Total N's	0

Number of excursions during this month: 0

(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are cumulative). An excursion' is any day in which the water quality parameter(s) fall below the minimum set by the State.

Reference	
<b>Minimum Water Quality Parameter(s) as set by State:</b>	
pH	7.3

Print Name: Steven Bethke  
 Signature: Steven Bethke  
 Date: 5-3-22

Send to DWP within 10 days after end of sampling period  
 DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350  
 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp