

Water Quality Parameter Monitoring Form

OREGON HEALTH AUTHORITY

Lead & Copper Rule Corrosion Control

Day	Ph	Alk	Phos	Sili	Y/N	<< Have	
1						Minimums	County: Josephine Agency: 5
2					1	Been Met	Entry Point
3					1	for this day	A
4	7.7				Y		PWS ID 4100971
5							Cave Junction, City of
6	7.5				Y	1	
7					1		Sample Period:
8						1 1	Month/Year Mar. 2025
9					1	1 '	
10	7.6				Υ		
11	7.6		1		Y	1	Number of excursions during this month: 0
12						1	
13					1		(Over 9 excursions in 6 months is a violation. Entry
14	7.5	************			Y	1	Point and Distribution excursions are cumulative). An
15							excursion' is any day in which the water quality
16						1	parameter(s) fall below the minimum set by the State.
17	7.5				Y		
18						7	
19	7.6				Y		
20	7.6				Y] [Reference
21						7	
22						7 1	Minimum Water Quality
23							Parameter(s) as set by State:
24							
25	Accession to the second				Y]	pH 7.3
26	7.4				Υ]	harmonia di managani di managa
27] [
28]	Ci 0 11 1/
29							rint Name: Steven Bethle
30						S	ignature: Steven Bethe
31							Date: 4-1-25

Send to DWP within 10 days after end of sampling period DHS, Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone: (503) 731-4381 Website: www.ohd.hr.state.or.us/dwp