

## neter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N
3		7.7	40			Y
8		7.5	35			Y
13		8.0	40			Y
16		7.9	50			Y
19		8.0	35			Y
23		8.0	45			Y
26		7.8	35			Y
30		7.8	35			Y
31		7.7	40			Y
			•	•		0

(N = No = Excursion)

Total N's

<Has sample
met the
minimums?</pre>

**ENTRY POINT** 

PWS ID: 41 0 1 0 7 2

System Name: <u>Johnson Creek</u>

Sample Period: January 2025\_

Number of excursions during this Sample Period = 0

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only  Minimum Water Quality  Parameters as set by					
рН					
Alk	30.0	(Alkalinity)			
PO4		(Orthophosphate)			
Other		()			

Print Name: JJ Olson

Signature: Osffrey Olson

Date: 2/5/2025

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/