

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location		рН	Alk PO4 Other Y		Y/N	<has sample<="" th=""><th>County: Douglas Agency: REGION 2</th></has>	County: Douglas Agency: REGION 2			
RS1	4-13 -4 Res	1210	Rs1	7.9				У	met the minimum(s)?	DISTRIBUTION	
		•							PWS ID 4101092 USFS TILLER RANGER STATION		
									Sample Frequ	d: April 2021 Month/Year Jency: Every 6 months Samples required: 1	
										cursions during this	
									(Number of locations when any WQP was less than the minimum.)		
									Excursions are	int and Distribution cumulative. Add Entry ribution Excursions to get period.	
				`					Referenc	e	
							,		Parame	m Water Quality ters as set by State:	
L	(N = No	= Exc	ursio	n) 1	Γotal	N's	Ø	B .	Jonethan Woody Junton Whooly 5/9/21	

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/