

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

ID#	Sample Location	рН	Alk	PO4	Other	Y/N	Has sample County: Douglas	Agency: REGION 2	
e53	R53 6-8-21 Sink	7.9				y	met the minimum(s)?	UTION	
			·			,	PWS ID 4101092 USFS TILLER RANGER STATION		
							Sample Period: June 2  Mon  Sample Frequency: Ever  Distribution Samples requ	y 6 months	
							Number of excursions duri Sample Period = (Number of locations when a was less than the minimum.)	ny WQP	
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.		
							Reference		
					,		Minimum Water Qual Parameters as set by pH 7.4		
	(N = No = Excu	rsion	) To	otal N	N's [	Ø	Print Name: Jane than la Signature: Jane La Date: 7-9-21	andy and	

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/