

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Lo	cation	рН	Alk	P04	Other	Y/N	<has sample<="" th=""><th>County: Douglas Age</th><th>ncy: REGION 2</th></has>	County: Douglas Age	ncy: REGION 2	
RSI	fes 1210	10-14	P. 7				Y	met the minimum(s)?	DISTRIBUT	ION	
				•				PWS ID 4101092 USFS TILLER RANGER STATION Sample Period: Ot 21 Month/Year			
								Month/Year Sample Frequency: Every 6 months Distribution Samples required: 1 Number of excursions during this Sample Period =			
								(Number of locations when any WQP was less than the minimum.) Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.			
	•							-Reference	<u> </u>		
						•			Water Quality ers as set by Sta .4	ate:	
	(N = No	o = Excu	ursion) To	otal N	l 's	Ø	Print Name: Signature: Date:	Jonathan Woody July Woody 11-7-21	dy	

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/