

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	pН	Alk	P04	Other	Y/N	Has sample County: Douglas Agency: REGION 2
1/10	tool ban sinn	8.0				بر	met the minimum(s)? DISTRIBUTION
			•				PWS ID 4101092
							USFS TILLER RANGER STATION
							Sample Period: <u>January 22</u> Month Year
	Ł						Sample Frequency: Every 6 months Distribution Samples required: 1
							Number of excursions during this Sample Period =
							(Number of locations when any WQP was less than the minimum.)
							Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
							Reference —
							Minimum Water Quality Parameters as set by State:
							pH 7.4
		·	_				
	(N = No = Excu	ırsion) To	otal I	v's	Ø	Print Name: July Worky Signature: July Worky Date: 7-8-77

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/