

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

ID#	Sample Lo	cation	рН	Alk	P04	Other	Y/N	County: Douglas Agency: REGION 2
Rs3	Admin s'hk	6-6-21	8.0			,	سو	met the minimum(s)?
								PWS ID 4101092
								USFS TILLER RANGER STATION
er interes						·		Sample Period: June 24  Month/Year
And the second							***************************************	Sample Frequency: Every 6 months
	:							Distribution Samples required: 1
is the physical production of a societable person of						_		Number of excursions during this Sample Period =
A PROPERTY FOR A STATE AND A S								(Number of locations when any WQP was less than the minimum.)
								Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
***************************************								Reference
						,		Minimum Water Quality Parameters as set by State:
-								pH 7.4
***************************************								·
(N = No = Excursion) Total N's							Print Name: Jonathan Woody Signature: July Date: 7-8-24	

Send to Drinking Water Program within 10 days after end of sampling period:

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/