

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	SIII	Y/N	< <have< th=""><th>1 2 2 3 3 4 4 2 2 2 3 4 4 4 4 4 4 4 4 4 4</th></have<>	1 2 2 3 3 4 4 2 2 2 3 4 4 4 4 4 4 4 4 4 4
1	77 0	- Nonevan	510000000000000000000000000000000000000			minimums	County: Clackemas Agency: CLACKAMAS COUNTY
2	100				$\vdash$	been met for	ENTRY POINT
3						this day?	EP-AA
4							PWS ID 4101125
5						You can only enter numbers or backspace or	
6			1				delete
7	W 1					Sample pe	riod: 09/2021
8	7.1					Month/Year -	
10						L.,	
11	$\dashv$					Number of excursions during this month: (Over 9 excursions in 6 months is a violation.	
12	$\dashv$						
13					$\dashv$		d Distribution excursions are
14					$\dashv$	veter quality p	In 'excursion' is any day in which the
	12				-	set by the Stat	erameter(s) fall below the minimum e.
16	1	7.1			$\dashv$		
17	7		+		-	. 5.6	
18	7	$\neg \neg$			-	Referen	1Ce
19		一十	$\neg \uparrow$		$\neg$	A.B.	inimum Water Quality
20		7		一十	-		arameter(s) as set by State:
21					7		
22 1!	7.3	Ť			$\neg$		pH <u>[ 7.1 ]</u>
23							
24						-	· ·
25							and the same of th
26							
27						Duluk Mas	Khara Daniel
28							ne: KARED DANIELSON
29 7	1.2						e: <u>Aukun Kanselinon)</u>
30						4,	one#: <u>/5/3<i>3-1</i>6/30-54/5</u> /9/2
31					7	Send to E sampling	OWP within 10 days after end of

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml