

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>
6-2		75					met the DISTRIBUTION minimums?
							PWS ID: 41 0 1 1 2 5 System Name: MTView CO-op A
69		7.6			·		Sample Period: 06/2023
							Sample Frequency: weeking Distribution Samples required:
Loib.		7.5					Number of excursions during this Sample Period =
-			•				(Number of locations when any WQP was less than the minimum.)
						- 1	Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period. For OHA use only Minimum Water Quality Parameters as set by
13		7.4					
.30	-	75					
							pH 7.; Alk (Alkalinity)
							PO4 (Orthophosphate) Other (
					-		
(N = No = Excursion) Total N's							Print Name: Ricky white Signature: RI. Wate Date: 7-2-23

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/