

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

ID#	Sample Location	pН	Alk	P04	other	Y/N	<has sample<="" th=""></has>
		7.2					met the DISTRIBUTION minimums?
							PWS ID: 41 0 1 1 2 5
		7.2					System Name: MTView CO-op A
							Sample Period: Feb 2024  Month/Year
							Sample Frequency: <u>wescy</u> Distribution Samples required:
		7.4					Number of excursions during this Sample Period =
							(Number of locations when any WQP was less than the minimum.)
		7.4					Note: Entry Point and Distribution
		<i>3</i>					Excursions are cumulative. Add Entry Point and Distribution Excursions to getotal for sample period.
			•				For OHA use only
		15					Minimum Water Quality Parameters as set by
			-				pH 7,1
							Alk (Alkalinity) PO4 (Orthophosphate)
1	3						Other (Ontrophosphate)
							Print Name: Ricky white
	(N = No = Exc	ursion	) To	tal N's	5		Signature: Ryl-White  Date: 3-2-2024

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/