

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	pH	Alk	Phos	Sili	Y/N	< <have< th=""><th>County: Clackamas Agency: CLACKAMAS COUNTY</th></have<>	County: Clackamas Agency: CLACKAMAS COUNTY	
1	7.2					minimums	ENTRY POINT	
2	11.01				\Box	been met for	ENTRIPOINT	
3				-		this day?	EP-B	
4							PWS ID 4101125	
5						You can only enter numbers or backspace or delete Sample period:		
6								
7	·							
8	7.3							
9						L	Wonan real	
10				• .		Number of ex	cursions during this month:	
11	:					(Over 9 excursions in 6 months is a violation. Entry Point and Distribution excursions are		
12				•				
13					·	cumulative). A	n 'excursion' is any day in which th	
14							arameter(s) fall below the minimum	
	72	·				set by the Stat	e.	
16								
17						Referer	nce	
18								
19		- 1					inimum Water Quality	
20						P	arameter(s) as set by State:	
21	-				_		pH 7.1	
22	111		-4				• •	
23					_			
24 25		\dashv		- :		·		
26	-+				-	and the same of th		
27			-+					
28			+			Print Name: MARKO DANIELSON		
29	71						e: Haren Hanielson	
30	1./		-		-	Date Pho	one#: <u>1503-430-545</u> 92	
31		-					OWP within 10 days after end of	
*			Total			sampling	period	

DHS-Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://oregon.gov/DHS/ph/dwp/index.shtml