

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

-	ID#	Sample Location	рН	Alk	PO4	other	Y/N	<has sample<="" th=""></has>
5-5			7.4					met the minimums? DISTRIBUTION
ĭ								PWS ID: 41 0 1 1 2 5  System Name: MTView 00-00 B
5-12			7.2					Sample Period: MAY 2023  Month/Year  Sample Frequency: Weekly  Distribution Samples required:  Number of excursions during this  Sample Period =
								(Number of locations when any WQP was less than the minimum.)
5-19			7.4		-			Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get otal for sample period.  For OHA use only  Minimum Water Quality Parameters as set by  pH 7:1  Alk (Alkalinity) PO4 (Orthophosphate) Other ()
					-		_	
,24 -			1.3					
-								
					-			Print Name: Ricky white
		(N = No = Excurs	ion)	Total	N's			Print Name: Ricky white Signature: RILME  Date: 5-31-23
	(	Send to Drinking Wa	iter Pr	oora	m wii	thin 1	በ ለ	ave after and of according

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/