

## Water Quality Parameter Monitoring Form

## Lead & Copper Rule Corrosion Control

ID#	Sample Location	рН	Alk	P04	other	Y/N	<has sample<="" th=""></has>
6-2		7.4					met the DISTRIBUTION minimums?
					··		PWS ID: 41 0 1 1 2 5
							System Name: MTView CO-00 B
6-9		7,5	:	-			Sample Period: 04/23
							Month/Year Sample Frequency: Weekly
						<del></del>	Distribution Samples required:
-16		7.4					Number of excursions during this Sample Period =
							(Number of locations when any WQP was less than the minimum.)
23		7.6					Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.
							For OHA use only
30		7.5	<u> </u>	1			Minimum Water Quality Parameters as set by
			:				pH 7.1 Alk (Alkalinity)
			-				PO4 (Orthophosphate)
							Other
	(N = No = Excu	(goier	Tota	I N's			Print Name: Ricky white Signature: Inlind
	W- 110 EXOR	olony-	1. YE	1.14-2.	Ė_		Date: 7-2-23

Send to Drinking Water Program within 10 days after end of sampling period: OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/