

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N
6		7.50				Y
20		7.50				Y
	(N = No = Excursion) Total N's					

<Has sample
met the
minimums?</pre>

ENTRY POINT

PWS ID: 41 0 1 1 4 8

System Name: Columbia Acres

Sample Period: NOV 2024

Sample Frequency: <u>Every 2 weeks</u>

Entry Point Samples required: 2

Number of excursions during this Sample Period = <u>0</u>

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only						
Minimum Water Quality Parameters as set by						
рН	7.2					
Alk		(Alkalinity)				
PO4		(Orthophosphate)				
Other		()				

Print Name: JJ Olson

Signature: Jeffrey Olson

Date: 12/10/2024