

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	Sample Location (Other than Entry Point)	рН	Alk	PO4	other	Y/N
9		7.4				Y
23		7.3				Y
(N = No = Excursion) Total I					<u> </u>	0

<Has sample
met the
minimums?</pre>

**ENTRY POINT** 

PWS ID: 41 0 1 1 4 8

System Name: Columbia Acres

Sample Period: Sept 2025

**Entry Point Samples required: 2** 

Number of excursions during this Sample Period = <u>0</u>

(Number of locations when any WQP was less than the minimum.)

Note: Entry Point and Distribution Excursions are cumulative. Add Entry Point and Distribution Excursions to get total for sample period.

For OHA use only						
Minimum Water Quality Parameters as set by						
pH 7.2						
Alk	(Alkalinity)					
PO4	(Orthophosphate)					
Other	()					

Print Name: Curtis Olson

Signature: Curtis Olson

Date: 10/10/2025