

## Water Quality Parameter Monitoring Form

## **Lead & Copper Rule Corrosion Control**

Day	рН	Alk	Phos	Other Y/N		
1		e periodici e per el la la cola liberaria de la la cola de periodici e la cola de la cola de la cola de la col			minimums	
2					been met for this day? PWS ID: 41 0 / 2 3 3	
3					System Name: Deer John Waterworks	
4						
5					Entry Point: Hose 8.6	
6	7.2				Sample Period: <u>JUNE</u> Z022	
7					Month/Year	
8					Number of excursions* during this month:	
9					(Count the number of days when any WQP was	
10					less than the minimum required)	
11						
12					Total excursions during the previous 5 months:	
13					(Over 9 excursions in 6 months is a violation. Entry	
14					Point and Distribution excursions are cumulative )	
15					For OHA use only	
16					To or the decimy	
17					Minimum Water Quality	
18					Parameters as set by	
19						
20					pH	
21					Alk (Alkalinity)	
22					PO4 (Orthophosphate)	
23					Other(	
24						
25						
26						
27	7.1				Print Name: Just Made 11	
28					Print Name: Mohille Signature:	
29					Date: 7-9-22	
30						
31					Send to DWP within 10 days after end of sampling period	
(No = 1	No = N = Excursion) Total N's					

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/