

Water Quality Parameter Monitoring Form

Lead & Copper Rule Corrosion Control

Day	рН	Alk	Phos	Other	Y/N	< <have< th=""></have<>
1						minimums ENTRY POINT
2						been met for this day? PWS ID: 41 O i Z 3 3
3						System Name: Over Island Water Works
4						
5						Entry Point: Hose Bib
6						Sample Period: Octobe Zozz
7						Month/Year
8						Number of excursions* during this month:
9						(Count the number of days when any WQP was
10	7.2					less than the minimum required)
11						
12						Total excursions during the previous 5 months:
13						(Over 9 excursions in 6 months is a violation. Entry
14						Point and Distribution excursions are cumulative)
15						For OHA use only
16						Tel elli des elli
17						Minimum Water Quality
18						Parameters as set by
19						
20						pH (Allea line if a)
21						Alk (Alkalinity)
22						PO4 (Orthophosphate)
23						Other()
24	7.1					
25	•					
26						
27						Print Name: Trans 14 to 15
28						Print Name: Justa Mc Miller Signature: Jesta Me men Date: 11/10/22
29						Date: 11/10/22
30				,		
31						Send to DWP within 10 days after end of
(No = N	No = N = Excursion) Total N's					sampling period

OHA Drinking Water Program, PO Box 14350, Portland, OR 97293-0350 Phone (971) 673-0405 Website: http://healthoregon.org/dwp/